


STATUS OF SURFACE WATER BODIES ACCORDING TO OVERALL HYDROMORPHOLOGICAL QUALITY INDEX

→ WATER 9

Escaut-Lys




Hydromorphological quality classes (2009 - 2013)

- High: ≥ 80
- Good: [60 - 80[
- Moderate: [40 - 60[
- Poor: [20 - 40[
- Bad: [0 - 20[
- Unknown

- River sub-basin boundary
- Surface water body boundary

Share of the number of water bodies for each quality class (%)



TOTAL: 354 water bodies